

Hot Fix Time/Temp

Swarovski Hot Fix - Time in Secs to Apply Heat

	Temperatures						
	250 F	265 F	285 F	300 F	320 F	340 F	
	120 C	130 C	140 C	150 C	160 C	170 C	
Wool (Trevira)	20	17	14	11	8	5	
Cotton	15	13	11	9	7	5	
Linen	15	13	11	9	7	5	
Wool	25	22	19	16	13	10	
Viscose	18	15	12	9	7	5	
Tulle	13	12	11	9	7	5	
Denim	25	23	21	18	15	12	
Lycra	25	21	17	13	9	5	
Cotton Jersey	15	13	11	9	7	5	
Syn. Suede	35	30	25	18	13	8	
Silk	14	13	11	9	7	5	
Synthetics	10	9	8	7	6	5	
Technical Fabric	10	9	8	7	6	5	
Fake Fur	60	50	40	30	20	10	